

Storm Water Construction General Permit Inspection Report

RWQCB - Region 5S

WDID # 5S03C337319

County: Amador

Del Rapini Const Inc

Pine Grove Bluffs

Owner's Name

Name of Development

28555 Rollins Lake Rd

Developer Contact and Phone NC #

Owner's Street Address

Ridge Road & Hwy 88

Colfax, CA 95713

Site Address

Owner's City, State and Zip code

Pine Grove, CA 95665

Del Rapini 530-389-8002

Site City, State, and Zip Code

Owner's contact person and phone #

1/24/2009

Rich Muhl

Date of Inspection

Inspection Conducted By

Time of Inspection

Dry Hot Clear ☒ Overcast Cold Raining

Status of Construction

Weather Conditions During Inspection (circle all that apply)

Type of Inspection:

Inspection in Conjunction with Other Permit

Permit Type: Construction

Termination Request

☒

Compliance Inspection

Outreach Inspection

Discharger/Facility Request

Follow-up to previous inspection ** Date of Previous Inspection

Other

Control Measures Checklist:

Yes - Evident on inspection No - Non evident on inspection

Areas of Concern:

Evidence of erosion?

Yes

No

☒

(hills, gullies, slips)

Dirt/sediment tracked in streets?

☒

Evidence of dewatering?

☒

Other

The SWPPP was not reviewed

Storm Water Samples Collected?

☐

☒

Yes

No

Non-Storm Water Discharge or Evidence
of Non-Storm Water Discharge Observed?

☐

☒

Yes

No

Separate Inspection Report Written?

☐

☒

Yes

No

Updated SWPPP on Site?

☒

☐

Yes

No

Inspection Summary (complete only if no separate inspection report is written):

During the site inspection staff observed significant storm water management problems on the construction site. These problems included the general lack of an effective combination of sediment and erosion control BMPs in many areas of the project, poorly protected drain inlets and turbid storm water discharge from the construction site at two locations (see inspection photographs). The inspection was conducted early in morning after a significant rain event which occurred the night before the inspection.

Signature

Date Entered:

Entered By:

Senior Review:

SJM

1/24/09



Figure 1: One of the many areas where soil is slumping on the steep slopes on the northern side of the project



Figure 2: Overview of one portion of the project



Figure 3: Overview of another portion of the project



Figure 4: Lack of an effective combination of erosion and sediment control BMPs



Figure 5: Lack of effective BMPs on the slopes and lack of BMPs in a defined drainage channel



Figure 6: Lack of an effective combination of erosion and sediment control BMPs

1/24/09



Figure 7: Lack of an effective combination of erosion and sediment control BMPs



Figure 8: Partially protected slope Note: the turbid discharge leaving the site which flows directly under the roadway and into the creek



Figure 9: Poorly protected slopes



Figure 10: Lack of an effective combination of erosion and sediment control BMPs on a portion of the project



Figure 11: Lack of an effective combination of erosion and sediment control BMPs on another portion of the project



Figure 12: Lack of an effective combination of erosion and sediment control BMPs on still another portion of the project

1/24/09



Figure 13: Inadequate BMPs at a location where storm water flows from the site into a down drain which directly flows under the roadway and into the creek



Figure 14: Inadequate BMPs at another one of the discharge areas



Figure 15: Storm water discharge from the site entering the culvert which flows under the highway and directly into the creek



Figure 16: Storm water flowing on the site along Ridge Road



Figure 17: Poorly protected drain inlet along Ridge Road



Figure 18: Another view of the poorly protected drain inlet

1/24/09



Figure 19: Another view of the same area



Figure 20: Pondered storm water around another drain inlet



Figure 21: Still another view of the same area



Figure 22: Lack of an effective combination of erosion and sediment control BMPs on another portion of the project



Figure 23: Storm water from the site mixing in the creek at one of the discharge locations Note: the storm water from the site is on the left hand side of the photograph



Figure 24: Storm water from the site mixing in the creek at another discharge location Note: the storm water from the site is on the left hand side of the photograph

1/24/09



Figure 25: Another view of the same area